

## How to Make a Pogo Pin Test Jig

Created by Tyler Cooper



https://learn.adafruit.com/how-to-make-a-pogo-pin-test-jig

Last updated on 2022-12-01 01:53:19 PM EST

© Adafruit Industries Page 1 of 11

## Table of Contents

Overview	3
Preparation	3
Arduino Shield Jigs	5
The Code	8
Testing	9
Advanced Pogo Jigs	10
Support Forums	11

© Adafruit Industries Page 2 of 11

#### Overview



If you end up buying a pick and place to assemble PCBs (or even if you're doing it by hand) you'll need to test out your boards! If you have an assembler do it for you, its still probably a good idea to have a jig you can give them. A good jig will tell you whats going right and whats going wrong.

In this tutorial I will show how I designed a very basic jig with a "tested good" audible indicator. The board its testing is very simple but the basic premise can be expanded to large projects with ease.

## Preparation

I like to use a victim PCB to make jigs - FR4 is strong and you already have a template. You'll also need some standoffs and some pogo pins.

© Adafruit Industries Page 3 of 11



The spring-loaded ('pogo') pins I prefer are about 0.5" long and have a spear point. They also fit snugly into 'standard' 0.035" (0.9mm) drill holes so they are easy to insert and stand up straight. We now carry these pogo pins in the Adafruit shop! (http://adafru.it/394) They're called "P75-LM" type, you can also pick them up on ebay. I don't use the socket holders because - well - I dont. But if you're building something that will be used for a long time by clumsy people its probably a good idea.



See above for a handy reference diagram for the kinds of heads you can get!

This board already has 4 x 2-56 sized mounting holes so its easy to attach standoffs.

© Adafruit Industries Page 4 of 11



Choose the standoffs so that the tips of the pogo pins are above the standoff part but below the end of the screw.



# Arduino Shield Jigs


I will be using <u>an Arduino to make this jig</u> (). Arduinos are very standard, easy to power and are a breeze for short projects like this. You'll also want a <u>proto shield PCB</u> ()

I think I'll put the victim...like this!


© Adafruit Industries Page 5 of 11




Mark and drill the mounting holes - four in this case. Luckily (or on purpose???) I placed the mounting holes on 0.1" boundaries.



© Adafruit Industries Page 6 of 11




Solder wires from each pogo pin to a matching pin on the shield. For this SD card interface I connected the SPI pins to the SPI port. Then the output of the 3.3v regulator goes to an analog pin. I also connected the card detect pin up so I can tell when a board is being tested.



A piezo buzzer is connected to pin #9 (underneath the PCB).

© Adafruit Industries Page 7 of 11



#### The Code

The code for the project is below and available on GitHub.

# See the files for this project on GitHub

```
// SPDX-FileCopyrightText: 2019 Limor Fried for Adafruit Industries
// SPDX-License-Identifier: MIT
 SD card breakout tester!
 Uses fat16lib's fantastic FAT library
  tests:
  1. CD pin works (goes low when card inserted)
  2. 3.3V LDO output is in proper range
 3. Can communicate with card
#include <SD.h>
Sd2Card card;
#define CD 15 // A1 (D15) -> CardDetect
#define LDO 0 // analog 0
void setup()
 // initialize the digital pin as an output:
  Serial.begin(9600);
  digitalWrite(CD, HIGH); // pull up on CD
void loop()
```


© Adafruit Industries Page 8 of 11


```
Serial.println("waiting for SD card detect");
  while (digitalRead(CD)) {
  Serial.print('.');
  delay(100);
  Serial.println("Detected Card!");
  // first check 3.3V regulator
  int a = analogRead(LD0);
  if ((a > 710) || (a < 650)) {
    // LDO not in the right range
    Serial.println(a);
    return;
  }
  Serial.println("3.3V LDO ok");
  // try to talk to the card
  uint8_t r = card.init(1);
  if (!r) {
    // failed to talk to SD card :(
    Serial.println(r, DEC);
    return;
  Serial.println("Card interface ok");
  // beep to indicate all is good
  tone(9, 4000, 500);
  delay(1000);
}
```

## **Testing**

Now the fun part! When a board is ready to test, insert a uSD card, and simply slip it into the orienting 'registration' standoffs and press down to make contact with the pogo pins. The Arduino will automatically detect when the CD pin is shorted to ground (good) and begin the test procedure. If all is good, it will beep!

© Adafruit Industries Page 9 of 11





Beep!

# Advanced Pogo Jigs

For more complicated projects, you may need to have a complicated testing procedure in which case we can make multi-step testers that also keep the PCB held down with little ears!

© Adafruit Industries Page 10 of 11



(We totally saw this and stole the idea from someone online but we can't find the link anymore, sorry!)

The plastic pieces hold down the PCB against the pogo bed. This tester, when used with a little batch script, performs the following test:

- 1. Reprograms the board's fuses and flash with a bootloader (via the ISP port). For this part we're using the Arduino as an ISP programmer (there's a sketch that does this)
- 2. The computer then bootloads (via USB) a pin-by-pin testing program
- 3. Once the board indicates the test completed, the computer erases the testing program

## **Support Forums**

Support Forums ()

© Adafruit Industries Page 11 of 11