


## INSPECTION LIST

- Perform cosmetic inspection.
- Verify label reads with VL-CBL-8002.
- Verify that connectors are installed the correct direction.
- Verify that connectors are properly terminated.
- Verify length of cable C (including connector) are  $13'' \pm .25$ , verify length of cable A & B (including connector) is  $19'' \pm .25$
- Verify pin 1 arrows align with red strips.
- Verify pins 10B to 16B have a twist in the cable.
- Verify that there are no connections to pins 7 to 10 on XMA10M.
- Verify that there is no polarization key on 34 pin connector.
- Verify that there is a polarize key on the 40-pin connector.
- Verify that IDC connector is properly crimped.

## ASSEMBLY



## ASSEMBLY

