

# ERRATA SHEET



N° 10081AERRA

PL=39

## ILD6070 and ILD6150 Data Sheet Update

Attached you find the Errata Sheet N° 10081AERRA  
Please forward this information to your customers as soon as possible.

**In case your customer has any questions or concerns on this Errata Sheet  
please contact directly the author.**

Complete customer information, e.g.: product list, Customer Info Package is also available on the Infineon intranet at:

[http://goto.infineon.com/ci\\_docs/](http://goto.infineon.com/ci_docs/)

Please address any questions on this issue to author:

Name, Surname	Hutsteiner, Thomas
Department	IFAG PMM ACL PM
Location	MUC
Telephone	+49-89-234-24747
E-Mail	<a href="mailto:thomas.hutsteiner@infineon.com">thomas.hutsteiner@infineon.com</a>

# ERRATA SHEET



N° 10081AERRA

## ILD6070 and ILD6150 Data Sheet Update

**Subject of Change:** ILD6070 and ILD6150 Data Sheet Update

<b>Products affected:</b>	<b>Type</b>	<b>SP N°</b>	<b>OPN</b>	<b>Package</b>
	ILD6070	SP000955324	ILD6070XUMA1	PG-DSO-8
	ILD6150	SP000955332	ILD6150XUMA1	PG-DSO-8

**Reason of Change:** Errata in Data Sheet Rev. 3.1

<b>Description of Change:</b>	<u><b>Old</b></u>	<u><b>New</b></u>
	Data Sheet Rev 3.1	Data Sheet Rev. 3.2

**Time Schedule:** 04-08-2014

<b>Documentation:</b>	Errata sheet Data Sheet ILD6070 Rev 3.2 Data Sheet ILD6150 Rev 3.2
-----------------------	--

If you have any questions, please do not hesitate to contact your local Sales office.