



May.1.2023 Copyright 2023 HIROSE ELECTRIC CO., LTD. All Rights Reserved.
 In case of consideration for using Automotive equipment / device which demand high reliability, kindly contact our sales window correspondents.



May.1.2023 Copyright 2023 HIROSE ELECTRIC CO., LTD. All Rights Reserved.
 In case of consideration for using Automotive equipment / device which demand high reliability, kindly contact our sales window correspondents.



Notes 5 1 reel : 1000 connectors.


| | | | |
|------------|-------------|------------------|-----|
| HRS | DRAWING NO. | EDC-150678-22-04 | 2/3 |
| | PART NO. | FX8-140S-SV(22) | |
| | CODE NO. | CL578-0207-1-22 | |
| | | | |

May.1.2023 Copyright 2023 HIROSE ELECTRIC CO., LTD. All Rights Reserved.
In case of consideration for using Automotive equipment / device which demand high reliability, kindly contact our sales window correspondents.


【 Precaution 】

When a board with multiple connectors mounted is mated, the connector may be damaged or deformed.
Please divide one side of the board so only one connector is mated per board.

OK



NG



HRS

| | |
|-------------|------------------|
| DRAWING NO. | EDC-150678-22-04 |
| PART NO. | FX8-140S-SV(22) |
| CODE NO. | CL578-0207-1-22 |

3/3