FS-1

FACE SHIELD WITH LATEX HEADBAND



Cleaning Instructions:

This face shield may be used multiple times by the same person.

- 1. Carefully wipe the inside and then the outside of the visor using a clean cloth saturated with neutral detergent solution, rinse if needed.
- 2. Carefully wipe the outside of the visor using a clean cloth or wipe saturated with hospital disinfectant solution; be sure it remains wet for the required contact time. The CDC recommends a .1% chlorine solution. Carefully avoid the foam cushion and elastic strap as they may not be tolerant to disinfectants.
- 3. Wipe the outside of visor with clean water to remove residue.
- 4. Fully dry (air dry or use clean absorbent towels).

Materials:

CLEAR SHIELD

Clear fog-free, glare-free polyester film, .007" thick, with or without removable protective film

ELASTIC HEADBAND

.75-1.25" wide braided or knit elastic latex fabric

BROW FOAM

1" to 1.375" thick (1.125" x 9" surface) adhesive backed polyurethane foam

NOT MRI SAFE

Manufacturer:

SOUND DEVICES, LLC E7556 State Road 23 and 33 Reedsburg, WI 53959 Phone: 1-800-505-0625

Local Phone: +1 (608) 524-0625

Fax: +1 (608) 524-0655

